


R. H. Adair



	FOAM MEMBRANE INC. AT THE BOTTOM OF SOGG. (2x2 oz).	
D	GELCOAT SEAL DID NOT RUN ALL THE WAY UP RUDDER TUBE	
C		
B	UPDATED WITH LLOYD'S RECOMMENDATIONS	
A		
ISSUE		MODIFICATION



INSTALLATION OF STEERING GEAR TO SURVEYOR'S SATISFACTION

48 3/4"

10MM BULKHD. 2

4" APPROX.

20"x2"x2" PLYWOOD SKGGY STIFFENER.

FROM TOP OF RUDDER.

1/4"x1/4" MIS BOX 'T' CHAIRS

FILLITE AND RESIN MIXTURE.

2x2 OR 2x1 MEMBRANE

WATER LINE

DETAIL FROM DWG NO. M81052

THIS DRAWING IS NOT TO BE USED FOR PRODUCTION PURPOSES