

31. Make bunk slide easy.
32. Bigger hole for bilge access.
33. Sumlog outboard and wire light. skin fitting under galley.
34. Cushion retaining lips for'd end quarter berth.
35. Cover fuses (vinyl)
36. Chart table door and shelf
37. Chart table  $\frac{1}{8}$ " fiddle gap.
38. Size of chart stowage
39. a) Cooker top and cave under cooker  
b) Cooker fall out
40. Move aft window aft by 4"
41. Change overhead buttons.
42. Fiddlw on loo basin.
43. Treadmaster on forecabin step
44. Small shelf over galley
45. Increase size of door below sink
46. Fit winch handle pocket at for'd end of cockpit.
47. Decide whether genoa winches should be increased in size.
48. Raise lockers in for'd cabin at least aft of deck well by approx. 5"
49. Stop on chain locker door.
50. Water filler further outboard.
51. Raise lower lip on aft cabin cave lockers.
52. Aft chain plate needs timber pad.

Peter Barton to deal with following:-

1. Leave out aft fairlead in toerail.
2. Raise toerail pots by 1" and secure better to rail.
3. Small cleat on mast for burgee halliard.
4. Confirmation from Isomat that mast base arrangement is O.K.

CIRC.

*W. VINEY.*

*P. BARTON*

*D. MOORE.*

*R. BENNETT.*